

CqC

THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re application:

Roll et al.

Patent No.:

6,869,095

Issue Date:

March 22, 2005

Docket No.: 18789-00121

Title:

TRAILER COUPLER ASSEMBLY

Attn: Certificate of Correction Branch

Commissioner for Patents

P.O. Box 1450

Alexandria, VA 22313-1450

CERTIFICATE OF MAILING UNDER 37 C.F.R. 1.8

Dear Sir:

I hereby certify that these papers are being deposited with the United States Postal Service with sufficient postage as first class mail on the date below and in an envelope addressed to: Attn: Certificate of Correction Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

Certificate

AUG 0 3 2006

of Correction

Date of Deposit

(Typed or Printed Name)

Documents Enclosed:

- 1. Request for Certificate of Correction Under 35 U.S.C. 254 Patent Office Mistake (1 page)
- 2. Certificate of Correction (1 page)
- 3. Return Receipt Postcard

CERTIFICATE OF MAILING UNDER 37 C.F.R. 1.8

certify that these documents are being deposited with the United States Postal Service with sufficient postage as first class mail on this and day of July, 2006 and in an envelope addressed to: Commissioner of Patents, P.O. Box 1450, Alexandria, VA 22313-1450

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re application:

Roll et al.

Patent No.:

6,869,095

Issue Date:

March 22, 2005

Docket No.: 18789-00121

Title:

TRAILER COUPLER ASSEMBLY

REQUEST FOR CERTIFICATE OF CORRECTION UNDER 35 U.S.C. 254 - - PATENT OFFICE MISTAKE

Attn: Certificate of Correction Branch

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313

Dear Sir:

Attached is a Certificate of Correction Form (Form PTO/SB/44) to correct minor typographical errors within the claims of the patent.

We believe there is no fee due for this Certificate of Correction due to the unintended Patent Office mistake. However, if that is not correct, please charge any required fees to our Deposit Account No. 13-0265.

Respectfully submitted,

7-27-06 Date

Robert H. Earp III, Reg. No. 41,004

McDONALD, HOPKINS CO., L.P.A. 600 Superior Avenue, E.

Cleveland, OH 44114-2653

(216) 430-2003

PTO/SB/44 (04-05) Approved for use through 04/30/2007. OMB 0651-0033 U.S. Patent and Trademark Office; U.S. DEPARTMENT OF COMMERCE Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number. (Also Form PTO-1050)

HINITED STATES DATENT AND TDADEMARK OFFICE

CERTIFICATE OF CORRECTION
Page <u>1</u> of <u>1</u>
PATENT NO. : 6,869,095
APPLICATION NO.: 10/687,168
ISSUE DATE : March 22, 2005
INVENTOR(S) : Roll et al.
It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:
Col. 5, claim 1, line 20, remove the word "bone" and replace with "bore"

MAILING ADDRESS OF SENDER (Please do not use customer number below):

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.